








EXPLANATION

-  Trench Rim
-  Road
-  Fence
-  Fill Area
-  Drum Area



Source: Landsburg PLP Steering Committee 1991

FIGURE **3-5**
DRUM REMOVAL
CONDUCTED DURING ERA
LANDSBURG MINE SITE/RI/FS/WA